



REALIGNING EASTBOUND INTERSTATE 4 (I-4) EXIT TO LAKE MARY BOULEVARD

FINANCIAL ID: 439682-2-52-01


CURRENT

Current configuration of the eastbound I-4 exit to Lake Mary Boulevard is two right turn lanes: one to eastbound Lake Mary Boulevard and one to a right-turn-only lane to Lake Emma Road.



UNDER CONSTRUCTION

The configuration of the eastbound I-4 exit to Lake Mary Boulevard will be two right turn lanes. Both lanes take drivers to eastbound Lake Mary Boulevard. Once motorists are traveling on eastbound Lake Mary Boulevard, they can then choose to move to the right-turn-only lane to Lake Emma Road.



More Info: I4Beyond.com